Maryland Historical Trust

Maryland Inventory of Historic Properties number:	W.29-51	- M: a4	-41
Name: Parreyville Rd. O	vertrile	L Sereca	.Creek

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

Eligibility Recommended	MARYLAND HISTO		Not Recomn	mendedX
Criteria:ABC	D Considerations:	_ABC _	DE _	FGNone
Comments:				· ·
Reviewer, OPS:_Anne E. Brude		Dat	e:3 April	2001
Reviewer, NR Program:Peter	E. Kurtze	Dat	e:3 April	2001

The state of

MHT Number-M:29-51

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. M 28 over tributary of Seneca Creek

ivaline and STIA ivo. ivi 28 over thousary of Seneca Creek
Location: Street/Road Name and Number: Berryville Road over tributary of Seneca Creek
City/Town: Rockville Vicinity X
County: Montgomery
Ownership:State_X_CountyMunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: X yes no
NR listed districtNR determined eligible districtX locally designatedother Name of District Seneca National Register and Local Historic District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X Metal Girder X Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased
Metal Suspension
Matal Arab

Metal C	Cantilever
Concret	
	Concrete ArchConcrete SlabConcrete Beam
F	Rigid Frame
(Other Type Name

Description:

Describe Setting:

Bridge No. M 28 carries Berryville Road east-west over a tributary of Seneca Creek, in Montgomery County, Maryland. Both approaches are level and curved. The area around the bridge is rural and heavily wooded.

Describe Superstructure and Substructure:

Bridge No. M 28, built in 1930, is a single span structure with a total length of 27'-6" and carries Berryville road over Seneca Creek tributary. This bridge has recently been rehabilitated with a new corrugated galvanized metal deck, weathering steel guardrail, bituminous wearing surface and approach roadway, north abutment and wing wall, and concrete caps atop the south abutment. The bridge has a deck with of 17'-7", and a clear roadway width of 13'-7".

The superstructure is in good condition and shows little or no signs of deterioration. The substructure is in generally good condition. There is random vertical cracking and efflorescence on the south abutment and wingwalls. There is a large spall on the east side of the south abutment. The footing below, the old north abutment has been undermined. Rip-rap has recently been placed at the west end of the south abutment as well as along the new north abutment channel slopes.

Discuss Major Alterations:

This bridge has been modified, the north abutment is new, and the south abutment and wingwalls have new concrete caps. The deck has been replaced and a new guardrail installed.

History:

When Built: 1930 (reconstructed 1972) Why Built: Local transportation needs

Who Built: Unknown

Why Altered: Safety and structural needs

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

_A Events __Person __C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

It is unknown whether this bridge was constructed in response to significant events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether the construction and/or alteration of this bridge has had significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

This bridge is currently located within the Seneca National Register and Local Historic District. This bridge does not add to the visual or historic character of the district. The structures of this district represent mostly early 19th through early 20th century domestic dwellings, rural industry, and sections of the C&O Canal. Further information regarding this district is available at the Maryland Historical Trust.

Is the bridge a significant example of its type?

This bridge is not a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

No, this bridge does not appear to have retained the integrity of its primary character defining elements as defined within the Context Addendum. The north abutment has been replaced, the south abutment and wingwalls have been modified, guardrail replaced, and the deck has been replaced.

Should this bridge be given further study before significance analysis is made and Why?

Further research of this bridge is unnecessary. This bridge does not retain its integrity as defined by the Context Addendum, and is not eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Montgomery County

County Bridge Inspection Files.

Spero, P.A.C. & Company, and Louis Berger & Associates


1994 Historic Bridges in Maryland: Historic Bridge Context.

United States Geological Survey

1968 7.5' Seneca Quadrangle, photorevised 1984.

Surveyor:

Name: Jason D. Moser Date: September 1995
Organization: State Highway Admin. Telephone: (410) 321-2213
Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory # 1 34-41

Name M28 - BERRYVILLE RO OVER SENECA CREEK TRIE
County/State Montgomery / mo
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHA
Description APPROACH WEST
Number of 36 4



Inventory # <u>M: 24-</u>41

Name M28 - BERRYVILLE RD OVER SENELA CREEK TRIE County/State MontoomERY IMP
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description Approach East
2 4

2 M ___ X_ 38

Number 6 of 36



Inventory # <u>M: 24-41</u>

Name M28 - BERRYWHE RO OVER SENECA CREEK TRIB. County/State Montgomery MD
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHA
Description ELEVATION LOOKING SOUTH
Number of 316

S.



Inventory # M: 24-41

Name M28 - BERRUVILLE RO OVER SENECA CREEK TRIB.
County/State Montoomery /mo
Name of Photographer FRANK JULIANO
Date 2 45
Location of Negative SAR
Description ELEVATION LOOKING NORTH
11- 8
Number 12 of 36